Test Report

QDF26-0019919-03A1 **Date:** 2026-03-27

Client Name: Botanical Cube Inc.

Client Address: Room 11401, 14th Floor, Unit 1, Building 1, Moore Center, No. 34 Fenghui South Road, High-tech Zone, Xi'an City, Shaanxi Province

Sample Name: Fisetin

Sample Batch No.: BCI260224QHS98

Production Date: /

Manufacturer: /

Above information and sample(s) was/were submitted and certified by the client, SGS quoted the information with no responsibility as to the accuracy, adequacy and/or completeness.

Date of Sample Received: 2026-03-05

Testing Period: 2026-03-05 ~ 2026-03-25

Test Requested: Select test(s) as requested by the client.

Test Method(s): Please refer to next page(s).

Test Result(s): Please refer to next page(s).

SGS Approved Signatory

Scan to see the report

QDF26-0019919-03A1

Verification: check.sgsonline.com.cn

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

SGS Center, No.143, Zhuzhou Road, Laoshan District, Qingdao, Shandong, China 266101 t (86-532) 68999888 www.sgsgroup.com.cn
中国·山东·青岛市崂山区株洲路143号通标中心 邮编: 266101 t (86-532) 68999888 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

Test Report

QDF26-0019919-03A1 **Date:** 2026-03-27

Sample Description:

Sample No.	SGS Sample ID	Description
0002	QDF26-0019919-0002	sample in bag

Test Result(s):

Chemical Test(s)

Code	Test Item(s)	Unit(s)	Test Method(s)	Test Result(s) 0002	LOQ
1	* Lacquer flavin content	%	Provided by client	98.9	-
2	Lead(as Pb)	mg/kg	GB 5009.12-2023 II	ND	0.05
3	Total Arsenic(as As)	mg/kg	GB 5009.11-2024 Chapter I method II	ND	0.03
4	Total Mercury(as Hg)	mg/kg	GB 5009.17-2021 chapter I method III	ND	0.003
5	Cadmium(as Cd)	mg/kg	GB 5009.15-2023 Method II	ND	0.005

Remark:
- ND = Not Detected
- LOQ = Limit of Quantitation
- *Test items were carried out by SGS-CSTC Standards Technical Services (Tianjin) Co., Ltd. laboratory, were not included in the CNAS Accredited Schedule for the testing laboratory, were not included in the CNAS Accredited Schedule for our laboratory.

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com


SGS Center, No.143, Zhuzhou Road, Laoshan District, Qingdao, Shandong, China 266101 t (86-532) 68999888 www.sgsgroup.com.cn
中国·山东·青岛市崂山区株洲路143号通标中心 邮编: 266101 t (86-532) 68999888 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

Test Report

QDF26-0019919-03A1 **Date:** 2026-03-27

Spectrogram Photo:



Integration Results

No.	Peak Name	Retention Time min	Area mAU*min	Relative Area %
1		4.763	0.061	0.08
2	漆黄素	6.950	76.161	98.93
3		9.370	0.032	0.04
4		11.330	0.378	0.49
5		12.323	0.354	0.46
Total:				**100.00**

QDF26-0019919-0002

SGS authenticate the photo on original report only

Attention:
Chinese shall prevail in this report.
This Test Report supersedes the Test Report No. QDF26-0019919-03 issued by SGS-CSTC Standards Technical Services (Qingdao) Co., Ltd. Original test report will be invalid from today.
Unless otherwise stated the results shown in this test report refer only to the items tested.This document cannot be used for improper publicity, without prior written approval of the SGS. The test report shall only be used for scientific research, teaching, internal quality control.

*** End***

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

SGS Center, No.143, Zhuzhou Road, Laoshan District, Qingdao, Shandong, China 266101 t (86–532) 68999888 www.sgsgroup.com.cn
中国·山东·青岛市崂山区株洲路143号通标中心 邮编: 266101 t (86–532) 68999888 sgs.china@sgs.com

Member of the SGS Group (SGS SA)